UNITED STATES SECURITIES AND EXCHANGE COMMISSION

Washington D.C. 20549

FORM 8-K **CURRENT REPORT**

PURSUANT TO SECTION 13 OR 15(d) OF THE SECURITIES EXCHANGE ACT OF 1934

Date of Report (Date of earliest event reported): September 18, 2020

AVISTA CORPORATION (Exact name of registrant as specified in its charter)

Washington	<u>1-3701</u>	<u>91-0462470</u>
(State of other jurisdiction of incorporation)	(Commission file number)	(I.R.S. Employer Identification No.)
	1411 East Mission Avenue Spokane, Washington 9: (Address of principal executive offices, including 2)	
F	Registrant's telephone number, including area code: 5 Web site: http://www.myavista.com	509-489-0500
	None	
(Former name or former address, if changed since last report)		ince last report)
	Securities registered pursuant to Section 12(b) of	the Act:
Title of Each Class	Trading Symbols	Name of Each Exchange on Which Registered
Common Stock	AVA	New York Stock Exchange
Check the appropriate box below if the Forr following provisions:	m 8-K filing is intended to simultaneously satisfy the fili	ing obligation of the registrant under any of the
\square Written communications pursuant to Rule	e 425 under the Securities Act (17 CFR 230.425)	
\square Soliciting material pursuant to Rule 14a-	12 under the Exchange Act (17 CFR 240.14a-12)	
\square Pre-commencement communications pur	rsuant to Rule 14d-2(b) under the Exchange Act (17 CFI	R 240.14d-2(b))
\square Pre-commencement communications pur	suant to Rule 13e-4(c) under the Exchange Act (17 CFF	R 240.13e-4(c))
	nt is an emerging growth company as defined in Rule 40	05 of the Securities Act of 1933 (§230.405 of this
chapter) of Rule 12b-2 of the Securities Exc	change Act of 1934 (§240.12b-2 of this chapter).	Emerging growth company \Box
	v check mark if the registrant has elected not to use the eovided pursuant to Section 13(a) of the Exchange Act. [

Section 8 - Other Events

Item 8.01 Other Events.

There have been several fires in Avista Corporation's (Avista Corp. or the Company) region in early September. Avista Corp.'s investigation has determined that the primary cause of the fires in its region was extreme high winds, a weather event that triggered wildfires and affected electric utilities throughout the Pacific Northwest. To date, the Company has not found any evidence that the fires were caused by any deficiencies in its equipment, maintenance activities or vegetation management practices. However, the Company has become aware of instances where, during the course of the storm, otherwise healthy trees and limbs, located in areas outside its maintenance right-of-way, broke under the extraordinary wind conditions and caused damage to its energy delivery system at or near what is believed to be the area of origin of a wildfire. Those instances include what has been referred to as: the Babb Road fire (near Malden and Pine City, Washington); the Christensen Road fire (near Airway Heights, Washington); and the Mile Marker 49 fire (near Orofino, Idaho). Parallel investigations by the Department of Natural Resources are ongoing, and Avista Corp. is fully cooperating with these efforts.

Section 9 - Financial Statements and Exhibits

Item 9.01 Financial Statements and Exhibits.

(d) Exhibits

Date: September 21, 2020

104 Cover Page Interactive Data File (formatted as inline XBRL with applicable taxonomy extension information contained in Exhibits 101.)

SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned thereunto duly authorized.

(Registrant)	
/s/ Mark T. Thies	
Mark T. Thies	
ecutive Vice President,	
nancial Officer, and Treasurer	

AVISTA CORPORATION